

# Lead in School Drinking Water Report

## Washington State School for the Blind



Date(s) collected: 2024-03-23

Date(s) analyzed: 2024-04-02

Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Lead Test Result (ppb)
378595	Irwin School Building	Sink	Room 2	1 of 1	Water Fountain	37
378583	Irwin School Building	Sink	Room 11	1 of 1	Tap	33
378592	Irwin School Building	Sink	Room 1	1 of 1	Tap	11
378098	Irwin School Building	Sink	Room 14	1 of 1	Tap	8
378089	Irwin School Building	Sink - Multi-Compartment	Room 19	1 of 1. North sink	Tap	7
378088	Irwin School Building	Sink - Multi-Compartment	Room 19	1 of 2. South sink	Tap	6
378095	Irwin School Building	Sink	Room 16	1 of 1	Water Fountain	5
378580	Irwin School Building	Sink	Room 13	1 of 1	Tap	5

Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Lead Test Result (ppb)
378581	Irwin School Building	Sink	Room 13	1 of 1	Water Fountain	5
378585	Irwin School Building	Sink	Room 7	1 of 1	Tap	5
378586	Irwin School Building	Sink	Room 7	1 of 1	Water Fountain	5
378590	Irwin School Building	Sink	Room 3	1 of 1	Tap	5
378090	Irwin School Building	Sink	Room 18	1 of 1	Tap	4
378099	Irwin School Building	Sink	Room For 14	1 of 1	Water Fountain	4
378591	Irwin School Building	Sink	Room 4	1 of 1	Tap	4
378097	Irwin School Building	Sink	Room 15	1 of 1	Water Fountain	3
378587	Irwin School Building	Sink	Room 5	1 of 1	Tap	3
378593	Irwin School Building	Sink	Room 1	1 of 1	Water Fountain	3
378594	Irwin School Building	Sink	Room 2	1 of 1	Tap	3
378092	Irwin School Building	Sink	Room 17	1 of 1	Water Fountain	2
378094	Irwin School Building	Sink	Room 16	1 of 1	Tap	2
378091	Irwin School Building	Sink	Room 17	1 of 1	Tap	1
378093	Irwin School Building	Sink - Multi-Compartment	Staff Lounge	1 of 1	Tap	1
378101	Dry/Industrial Building	Fountain - Multi-Level	Room 1	1 of 1	Water Fountain	1
378584	Irwin School Building	Sink	Room 9	1 of 1	Tap	1
378080	Stenehjem Fitness Center	Fountain with Bottle Filler	Fitness Center	1 of 1	Water Fountain	<1

Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Lead Test Result (ppb)
378081	Stenehjem Fitness Center	Sink - Multi-Compartment	Recreation Room	1 of 1	Tap	<1
378082	Stenehjem Fitness Center	Fountain with Bottle Filler	Across From Gym	1 of 1	Water Bottle Filler	<1
378083	Stenehjem Fitness Center	Fountain with Bottle Filler	Across From Gym	1 of 1	Water Fountain	<1
378084	Stenehjem Fitness Center	Fountain - Multi-Level	Pool	1 of 1. Higher fountain	Water Fountain	<1
378085	Stenehjem Fitness Center	Fountain - Multi-Level	Pool	1 of 1	Water Fountain	<1
378086	Irwin School Building	Fountain with Bottle Filler	Next To Distance Learning Room	1 of 1	Water Bottle Filler	<1
378087	Irwin School Building	Fountain with Bottle Filler	Next To Distance Learning Room	1 of 1	Water Fountain	<1
378096	Irwin School Building	Sink	Room 15	1 of 1	Tap	<1
378100	Dry/Industrial Building	Fountain - Multi-Level	Room 1	1 of 1. Higher fountain 378	Water Fountain	<1
378573	Old Main/Administration	Sink - Multi-Compartment	Kitchen	1 of 2	Tap	<1
378574	Old Main/Administration	Sink	Kitchen	2 of 2	Tap	<1
378575	Old Main/Administration	Ice Machine	Kitchen Dishes Area	1 of 2	Other	<1
378576	Old Main/Administration	Sink	Kitchen Dishes Area	2 of 2	Sprayer	<1
378577	Old Main/Administration	Fountain with Bottle Filler	Ne Entry	1 of 1	Water Bottle Filler	<1

Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Lead Test Result (ppb)
378578	Old Main/Administration	Fountain with Bottle Filler	Ne Entry	1 of 1	Water Fountain	<1
378579	Stenehjem Fitness Center	Fountain with Bottle Filler	Fitness Center	1 of 1	Water Bottle Filler	<1
378582	Irwin School Building	Sink	Room 13	1 of 1	Water Bottle Filler	<1
378588	Irwin School Building	Fountain - Multi-Level	Hallway Across From Room 5	1 of 1. Higher fountain	Water Fountain	<1
378589	Irwin School Building	Fountain - Multi-Level	Hallway Across From Room 105	1 of 1	Water Fountain	<1
378596	Chapman Cottage	Sink - Multi-Compartment	Kitchen	1 of 1	Tap	<1
378597	Hall Cottage	Sink - Multi-Compartment	Kitchen	1 of 1	Tap	<1
378598	Clarke Cottage	Sink - Multi-Compartment	Kitchen	1 of 1	Tap	<1
378599	Watson Cottage	Sink - Multi-Compartment	Kitchen	1 of 1	Tap	<1

#### EXPLANATION OF TESTING AND RESULTS:

Results in this report represent sampling conducted by Washington State Department of Health. Per **RCW 28A.210.410** sampling and testing protocols, samples were collected as first-draw. Depending on size of the school(s) and number of drinking water fixtures, multiple dates for collecting samples may have been necessary to meet sampling and testing protocols. Above is information related to lead sampling for your school(s). For questions regarding testing and result, please email: [leadfreekids@doh.wa.gov](mailto:leadfreekids@doh.wa.gov)